Xhorse 35160DW Chip Instruction

Instruction: This chip used as replacement for ST company 35080xxx, 35160xx, 080D0xx, 160D0xx ,.etc types

Steps:

1. **Backup data**: Read and Save the dashboard original IC from 3 partitions(MEMORY+LONGID +ID LOCATION) or ALL option (ALL=MEMORY+LONGID+ID LOCATION), shown as sample picture

2. **Write data**: After replace original chip by Xhorse 35160xx chip, please write step1 saved 3 dumps to each partition on xhorse chip by VVDI PROG.

3. **Mileage correction**: 'Erase INC' button is for erasing the front 2 lines, after erase INC operation then select ALL or MEMORY option to Read data for verify, Reading data the front 2 lines should all '00', manually enter the targert mileage, then click Write option, operation completed.

4. **Verify data**: Soldering back the Xhorse chip to dashboard, check whether working well without red dot.